

07-10-2022 10:40:21

inCarDoc.com

BMW 528i 2009
WBANU53539C123508
AUTO,ISO15765-4(CAN11/500)
OBDII
Voltage: 13.0V

[Google Play: InCarDoc](#)

[App Store: InCarDoc \(PRO\)](#)

DIAGNOSTIC

GENERAL INFORMATION

DTCs: 0			
MIL: off			
	Time	Distance	Warm-ups
Active for the last:		0 mi.	
After last clear:		22 mi.	1

TROUBLE CODES

PENDING

P0174 System Too Lean Bank 2
P0171 System Too Lean Bank 1

EXTENDED DIAGNOSTICS

Engine(E8)

29E1 29E1 -> 29E1 (D1) Custom BMW error code (E8: Engine)

- pending fault present
- test readiness
- validated fault present